

VEHICLE INSPECTION REPORT

Vehicle VAT

Gearbox

DF69HAX

MAN TGL 7.160

Inspection

Fuel Type

Colour

| | | V5 | Buyer To Apply | | |
|-----------|-----------------------------|------------|-------------------|------------|----------|
| Details | | | | | |
| Reg. date | 21/02/2020 | VIN | WMAN03ZZ0LY409391 | Axle Combi | 4x2 |
| Year | 2020 | Body Style | Box Van | Rear Doors | Roller |
| Mileage | 235,461 Km Not Warranted | MOT Due | 31/01/2026 | Tail Lift | Tuckaway |
| | | Cab Type | DAY CAB | | |

AUTO

Plus VAT

SURROUND CAMERA SYSTEM

Diesel

WHITE

| Tyres | | | |
|---------------------|--|---|--|
| NSF | | | |
| Tyres NSF NSR | | , | |
| OSF | | | |
| OSR | | | |
| Spare | | | |
| | | | |

Features

Park assist camera

Photos















