

# VEHICLE INSPECTION REPORT

**YC63WCE**

## Mercedes-Benz Actros 3236

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 28/11/2013

Colour WHITE

Cab Type DAY CAB

Year 2013

VIN WDB9323072L775634

Gearbox MANUAL

Mileage 188,831 Km Warranted

Body Style Tipper Grab

Axle Combi 8x4

Fuel Type Diesel

MOT Due 31/12/2026

Rear Suspension Steel

TRANSCOVER BODY, ATLAS 130.2VGL CRANE (YEAR 2012), SHEETING SYSTEM, SURROUND CAMERA SYSTEM

### Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3

OSO4

## Features

- Park assist camera

## Photos












## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Thru Paint

2: Bumper Front  
Scratched  
Rusted





3: Bonnet  
Chipped  
Multiple Chips

4: Bumper Front  
Scratched  
Rusted



5: Bumper Front  
Scratched  
Rusted

6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
Over 100mm



7: Other  
N/A  
N/A

8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Other  
N/A  
N/A

10: Other  
N/A  
N/A



11: Door osf  
Chipped  
Edge Chip

12: Other  
N/A  
N/A



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

14: Screen Front  
Chipped  
Over 10mm



15: Door osf  
 Scratched  
 Over 25mm Not Thru Paint

Interior

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| Carpet Condition         | OK | Upholstery Condition                           | OK |
| Seat Condition           | OK | Odour                                          | -  |
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |