

# VEHICLE INSPECTION REPORT

**2625648**

## Iveco Eurocargo 180E25

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 01/01/2014

Year 2014

Mileage 8,481 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFA61TJ502625648

Body Style Flatbed

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Air

MOD654 FORM IN OFFICE


### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features


- Radio/CD
- Air conditioning

## Photos





## Condition Check



## Damage Photos



1: Wing nsf  
Chipped  
1 To 5



2: Door Moulding osf  
Scuffed (Unpainted)  
Over 100mm



3: Qtr Panel Arch Extension os  
Scuffed (Unpainted)  
Over 100mm



4: Qtr Panel Arch Extension ns  
Scuffed (Unpainted)  
Over 100mm

**Interior**

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		
Windows	OK			Radio	OK		
				Steering	OK		